

Structures at Fort Davis from the Second Fort Period (1867 -1891)

Structure #	Description	Current Condition
1	Lieutenant's Quarters	Roofed Structure
2	Captain's Quarters	Restored / Furnished
3	Lieutenant's Quarters	Roofed Structure
4	Lieutenant's Quarters	Roofed Structure
5	Captain's Quarters	Roofed Structure
6	Lieutenant's Quarters	Roofed Structure
7	Commanding Officer's Quarters	Restored/Furnished
8	Lieutenant's Quarters	Roofed Structure
9	Captain's Quarters	Roofed Structure
10	Lieutenant's Quarters	Roofed Structure
11	Lieutenant's Quarters	Roofed Structure
12	Captain's Quarters	Roofed Structure
13	Lieutenant's Quarters	Roofed Structure
	[Note for Structures 1-13] Each Officer's	
	Residence consisted of a main quarters, a separate kitchen behind the main building,	
	and a privy (outhouse) behind the kitchen.	
14	Two-Story Officers' Quarters	Roofed Structure
15	Two-Story Officers' Quarters	Ruin/Foundation
16	Non-commissioned Officers' Quarters	Ruin/Foundation
17	Married Men's Quarters	Ruin/Foundation
18	Two-Story Officers' Quarters	Roofed Structure
19	Ordnance Sergeant's Quarters / Signal Office	Ruin/Foundation
20	Enlisted Men's Barracks	Roofed Structure
21	Enlisted Men's Barracks	Roofed Structure
22	Enlisted Men's Barracks	Ruin/Foundation
23	Enlisted Men's Barracks	Ruin/Foundation
24	Band Barracks	Ruin/Foundation
25	Infantry Barracks	Ruin/Foundation
26	Enlisted Men's Barracks	Ruin/Foundation
27	Enlisted Men's Barracks	Ruin/Foundation
28	Post Chapel	Ruin/Foundation
29	Post Headquarters	Ruin/Foundation
30	Guardhouse	Ruin/Foundation
31	Bakery	Ruin/Foundation
32	Old Commissary Storehouse	Ruin/Foundation
33	Old Commissary Office	Ruin/Foundation
34	Old Quartermaster's Office and Storehouse	Ruin/Foundation
37	New Commissary Storehouse	Restored/Furnished

38	New Quartermaster's Storehouse	Ruin/Foundation
39	Forage House	Roofed Structure
40	Quartermaster's Corral	Ruin/Foundation
41	Cavalry corrals	Ruin/Foundation
45	Commanding Officer's Stables	Ruin/Foundation
46	Hospital	Roofed Structure
47	Hospital Storehouse	Roofed Structure
48	Hospital Steward's Quarters	Ruin/Foundation
49	Magazine	Roofed Structure
50	Hospital laundry (storehouse)	Ruin/Foundation
51	Hospital Woodhouse	Ruin/Foundation
52	Hospital Privy	Ruin/Foundation
61	Oil house	Ruin/Foundation
62	Sawmill shed	Ruin/Foundation
72	Unidentified ruin	Ruin/Foundation
73	Unidentified ruin	Ruin/Foundation
74	Temporary hospital	Ruin/Foundation
90	Waterpipe line	Ruin/Foundation
92	Cemetery	Ruin/Foundation
135	Possible stables ruins	Ruin/Foundation
136	Possible footbridge abutment	Ruin/Foundation
139	Earth closet	Ruin/Foundation
140	Lime Kiln	Ruin/Foundation
141	Spring Enclosure	Ruin/Foundation
142	Irrigation ditch	Ruin/Foundation
151	Kitchen for HB-18	Roofed Structure
152	Privy for HB-48	Ruin/Foundation
153	San Antonio to El Paso Road	Ruin/Foundation
200	Married men's quarters	Ruin/Foundation
228	Privy for HB-16	Ruin/Foundation
229	Privy for HB-15	Ruin/Foundation
232	Privy for HB-24	Ruin/Foundation
233	Privy for HB-25	Ruin/Foundation
240	Flagpole site, 1875-1884	Ruin/Foundation
241	Privy for HB-23	Ruin/Foundation
242	Privy for HB-22	Ruin/Foundation
243	Privy for HB-21	Ruin/Foundation
244	Privy for HB-20	Ruin/Foundation